



Bidng. construction seems to be a major time consumer & responsibility of the P.M.s. At the disposal, Inayat at least tells me he has to personally supervise all constr. & certainly the Markaz office coming up & which has to be completed by the end of the financial year i.e. 30/06 time.

Some ~~the~~ Kiln owners either seem really not to keep accounts or are covering up. Thus Khawer Kiln's owner ~~does~~ is not sure how many jinings they had last year - (says perhaps 4 - not enough demand) & then says all Thapairs have paishgi & none stayed on from the beginning & some out & have repaid their Paishgi & one joined them at the start & still with them (I am informed when I interview the Thapers.)

The Markaz Office is a depressingly wasteful & faulty design. An expensive r.c. cantilever provides a paltry shade to 2 side walls & a round hole for a ~~fan~~ mechanical exhaust (that will cost a lot, breakdown in 6 months & never be repaired) pays misleading lip service to climatic comfort, but basic things such as top vents & windows on 2 opposite sides to give cross ventilation & cool off the rooms is not provided.

